

In accordance with OSHA 29 CFR 1910.1200

BOSTIK WOOD TACKRevision Number 1

Revision date 15-Oct-2018 Supersedes date Not applicable

1. Identification

1.1. Product identifier

Product Name BOSTIK WOOD TACK

Other means of identification

Other information Not applicable

1.2. Relevant identified uses of the substance or mixture and uses advised against

Recommended use Adhesives

Restrictions on use No information available

1.3. Details of the supplier of the safety data sheet

Responsible Party

Bostik Inc.

11320 W. Watertown Plank Road Wauwatosa, Wisconsin 53226 USA

Phone: +1(800) 726-7845 (Domestic Toll Free) Phone: +1 (414) 774-2250 (International)

E-mail msds@bostik.com

1.4. Emergency telephone number

Emergency Telephone CHEMTREC (Chemical Transportation Emergency Center)

Chemtrec: 1-800-424-9300 (US), 1-703-527-3887 (Outside U.S.)

Rocky Mountain Poison Center: 1-866-767-5089

2. Hazard(s) identification

2.1. Classification of the substance or mixture

Serious eye damage/eye irritation	Category 2A
Skin sensitization	Category 1
Carcinogenicity	Category 2

Hazards not otherwise classified (HNOC)

Not applicable

2.2. Label elements

EMERGENCY OVERVIEW

Warning

Hazard statements

Causes serious eye irritation May cause an allergic skin reaction Suspected of causing cancer

US - EN Page 1 / 14

BOSTIK WOOD TACKRevision Number 1

Revision date 15-Oct-2018 Supersedes date 08-Apr-2025



Appearance Paste

Physical state Liquid

Odor Characteristic

Precautionary Statements - Prevention

Obtain special instructions before use

Do not handle until all safety precautions have been read and understood

Wear protective gloves/protective clothing/eye protection/face protection

Wash face, hands and any exposed skin thoroughly after handling

Avoid breathing dust/fume/gas/mist/vapors/spray

Contaminated work clothing must not be allowed out of the workplace

Precautionary Statements - Response

IF exposed or concerned: Get medical advice/attention

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing

If eye irritation persists: Get medical advice/attention IF ON SKIN: Wash with plenty of water and soap

If skin irritation or rash occurs: Get medical advice/attention

Wash contaminated clothing before reuse

Precautionary Statements - Storage

Store locked up

Precautionary Statements - Disposal

Dispose of contents/container to an approved waste disposal plant

2.3. Other Information

Causes mild skin irritation.

3. Composition/information on ingredients

3.1. Substances

Not applicable.

<u>Mixture</u>

Chemical name	CAS No.	Weight-%
Limestone	1317-65-3	15 - 40
Carbonic acid, magnesium salt (1:1)	546-93-0	1 - <5
Rosin	8050-09-7	1 - <5
Ethanolamine	141-43-5	0.1 - <1
Quartz	14808-60-7	0.1 - <1
Poly(oxy-1,2-ethanediyl), .alpha(4-nonylphenyl)omegahydroxy-, branched	127087-87-0	0.1 - <1
Vinyl acetate	108-05-4	0.1 - <1

US - EN Page 2 / 14

BOSTIK WOOD TACKRevision date15-Oct-2018Revision Number1Supersedes date08-Apr-2025

Zinc pyrithione	13463-41-7	<0.1
reaction mass of	55965-84-9	<0.1
5-chloro-2-methyl-2H-isothiazol-3-one and		
2-methyl-2H-isothiazol-3-one (3:1) [C(M)IT/MIT]		

^{*}The exact percentage (concentration) of composition has been withheld as a trade secret

4. First-aid measures

4.1. Description of first aid measures

General advice Show this safety data sheet to the doctor in attendance. IF exposed or concerned: Get

medical advice/attention.

Inhalation Remove to fresh air. If symptoms persist, call a physician.

Eye contact Rinse immediately with plenty of water, also under the eyelids, for at least 15 minutes.

Remove contact lenses, if present and easy to do. Continue rinsing. Keep eye wide open while rinsing. Do not rub affected area. Get medical attention if irritation develops and

persists.

Skin contact May cause an allergic skin reaction. Wash with soap and water. In the case of skin irritation

or allergic reactions see a physician.

Ingestion Rinse mouth. Never give anything by mouth to an unconscious person. Do NOT induce

vomiting. If swallowed, call a poison control center or physician immediately.

Self-protection of the first aider Avoid contact with skin, eyes or clothing. Wear personal protective clothing (see section 8).

4.2. Most important symptoms and effects, both acute and delayed

Symptoms Itching. Rashes. Hives. May cause redness and tearing of the eyes. Burning sensation.

Prolonged contact may cause redness and irritation.

Effects of Exposure No information available.

4.3. Indication of any immediate medical attention and special treatment needed

Note to physicians May cause sensitization in susceptible persons. Treat symptomatically.

5. Fire-Fighting Measures

5.1. Extinguishing media

surrounding environment.

Large Fire CAUTION: Use of water spray when fighting fire may be inefficient.

Unsuitable extinguishing media Do not scatter spilled material with high pressure water streams.

5.2. Special hazards arising from the substance or mixture

Specific hazards arising from the Product is or contains a sensitizer. May cause sensitization by skin contact.

chemical

Hazardous combustion products Carbon oxides.

US - EN Page 3 / 14

BOSTIK WOOD TACKRevision date15-Oct-2018Revision Number1Supersedes date08-Apr-2025

Explosion data

Sensitivity to mechanical impact None.

Sensitivity to static discharge None.

5.3. Advice for firefighters

Special protective equipment and precautions for fire-fighters

As in any fire, wear self-contained breathing apparatus pressure-demand, MSHA/NIOSH

(approved or equivalent) and full protective gear.

6. Accidental Release Measures

6.1. Personal precautions, protective equipment and emergency procedures

Avoid breathing dust/fume/gas/mist/vapors/spray. Ensure adequate ventilation. Evacuate

personnel to safe areas. Keep people away from and upwind of spill/leak.

Other information Refer to protective measures listed in Sections 7 and 8.

6.2. Environmental precautions

Environmental precautions Prevent entry into waterways, sewers, basements or confined areas. Do not flush into

surface water or sanitary sewer system. See Section 12 for additional Ecological

Information.

6.3. Methods and material for containment and cleaning up

Methods for containment Prevent further leakage or spillage if safe to do so.

Methods for cleaning upUse personal protective equipment as required. Soak up with inert absorbent material (e.g.

sand, silica gel, acid binder, universal binder, sawdust). Take up mechanically, placing in

appropriate containers for disposal. Clean contaminated surface thoroughly.

Reference to other sections See section 8 for more information. See section 13 for more information.

7. Handling and storage

7.1. Precautions for safe handling

safety practice. Avoid contact with skin, eyes or clothing. Ensure adequate ventilation. In case of insufficient ventilation, wear suitable respiratory equipment. Do not eat, drink or smoke when using this product. Take off contaminated clothing and wash before reuse.

7.2. Conditions for safe storage, including any incompatibilities

Storage Conditions Keep containers tightly closed in a dry, cool and well-ventilated place. Keep from freezing.

Recommended storage temperature Do not freeze. Keep at temperatures between 41 and 95 °F / 5 and 35 °C.

7.3 References to other sections

US - EN Page 4 / 14

BOSTIK WOOD TACKRevision date15-Oct-2018Revision Number1Supersedes date08-Apr-2025

Reference to other sections Section 10: STABILITY AND REACTIVITY

Section 13: DISPOSAL CONSIDERATIONS

8. Exposure Controls/Personal Protection

8.1. Control parameters

Exposure Limits

This product contains substances which in their raw state are powder form, however in this product they are in a non-respirable form. Inhalation of powder/dust particles is unlikely to occur from exposure to this product.

Chemical name	ACGIH TLV	OSHA PEL	NIOSH
Limestone	-	TWA: 15 mg/m ³ total dust	TWA: 10 mg/m³ total dust
1317-65-3		TWA: 5 mg/m³ respirable	TWA: 5 mg/m ³ respirable dust
		fraction	
		(vacated) TWA: 15 mg/m³ total	
		dust (vacated) TWA: 5 mg/m³	
		respirable fraction	
Carbonic acid, magnesium salt		-	TWA: 10 mg/m³ total dust
(1:1)			TWA: 5 mg/m³ respirable dust
546-93-0			
Rosin	TWA: 0.001 mg/m³ total resin	(vacated) TWA: 0.1 mg/m ³	TWA: 0.1 mg/m ³ Formaldehyde
8050-09-7	acids inhalable particulate	Formaldehyde	,
	matter		
	DS		
	RS		
Ethanolamine	TWA: 3 ppm	TWA: 3 ppm	IDLH: 30 ppm
141-43-5	STEL: 6 ppm	TWA: 6 mg/m ³	TWA: 3 ppm
		(vacated) TWA: 3 ppm	TWA: 8 mg/m³
		(vacated) TWA: 8 mg/m ³ (vacated) STEL: 6 ppm	STEL: 6 ppm STEL: 15 mg/m³
		(vacated) STEL: 6 ppm (vacated) STEL: 15 mg/m ³	STEE. 15 IIIg/III
Quartz	TWA: 0.025 mg/m³ respirable	TWA: 50 µg/m ³	IDLH: 50 mg/m³ respirable dust
14808-60-7	particulate matter	(vacated) TWA: 0.1 mg/m ³	TWA: 0.05 mg/m ³ respirable
		respirable dust	dust
		: (250)/(%SiO2 + 5) mppcf	
		TWA respirable fraction	
		: (10)/(%SiO2 + 2) mg/m ³	
		TWA respirable fraction	
Vinyl acetate	TWA: 10 ppm	(vacated) TWA: 10 ppm	Ceiling: 4 ppm 15 min
108-05-4	STEL: 15 ppm	(vacated) TWA: 30 mg/m ³	Ceiling: 15 mg/m ³ 15 min
		(vacated) STEL: 20 ppm	
		(vacated) STEL: 60 mg/m ³	

Chemical name	Argentina	Brazil	S.D. 594/1999	Colombia
Limestone	TWA-CMP: 10 mg/m ³ ;	-	TWA-LPP: 7 mg/m ³ ;free	-
1317-65-3			of Asbestos with <1%	
			free Crystalline Silica	
			TWA-LPP:	
			5 mg/m³;respirable	
			fraction	
Rosin	8	=	-	TWA: 0.001mg/m ³
8050-09-7				
Ethanolamine	TWA-CMP: 3 ppm;	TWA-LT: 3 ppm;	-	STEL: 6ppm

US - EN Page 5 / 14

BOSTIK WOOD TACK
Revision Number 1

Revision date 15-Oct-2018
Supersedes date 08-Apr-2025

141-43-5	STEL (CMP-CPT): 6	STEL: 6 ppm;		TWA: 3ppm
	ppm;			
Quartz	TWA-CMP: 0.05 mg/m ³ ;	TWA-LT: 0.025 mg/m ³ ;	TWA-LPP:	TWA: 0.025mg/m ³
14808-60-7	respirable fraction	respirable particulate	0.08 mg/m³;respirable	-
	•	matter	fraction	
Vinyl acetate	TWA-CMP: 10 ppm;	TWA-LT: 10 ppm;	-	STEL: 15ppm
108-05-4	STEL (CMP-CPT): 15	STEL: 15 ppm;		TWA: 10ppm
	ppm;			

Chemical name	Costa Rica	Peru	Uruguay	Venezuela
Rosin 8050-09-7	-	-	0.001 mg/m³ TWA (inhalable particulate matter, as total resin acids)	TWA:
Ethanolamine 141-43-5	STEL: 6ppm TWA: 3ppm	STEL: 6ppm STEL: 15mg/m³ TWA: 3ppm TWA: 7.5mg/m³	6 ppm STEL 3 ppm TWA	Skin STEL: 6 ppm TWA: 3 ppm
Quartz 14808-60-7	TWA: 0.025mg/m ³	TWA: 0.05mg/m ³	0.025 mg/m³ TWA (respirable particulate matter)	TWA: 0.025 mg/m ³
Vinyl acetate 108-05-4	STEL: 15ppm TWA: 10ppm	STEL: 15ppm STEL: 53mg/m³ TWA: 10ppm TWA: 35mg/m³	15 ppm STEL 10 ppm TWA	STEL: 15 ppm TWA: 10 ppm

8.2. Exposure controls

Appropriate engineering controls

Engineering controls Showers

Eyewash stations Ventilation systems.

Individual protection measures, such as personal protective equipment

Eye/face protection Wear safety glasses with side shields (or goggles). Avoid contact with eyes.

Hand protection Wear suitable chemical resistant gloves. The selection of suitable gloves does not only

depend on the material, but also on further marks of quality and various manufacturers.

Skin and body protectionWear suitable protective clothing.

Respiratory protection In case of insufficient ventilation, wear suitable respiratory equipment.

General hygiene considerations Wear suitable gloves and eye/face protection. Do not eat, drink or smoke when using this

product. Avoid contact with skin, eyes or clothing. Wash hands before breaks and

immediately after handling the product.

9. Physical and Chemical Properties

US - EN Page 6 / 14

BOSTIK WOOD TACKRevision date15-Oct-2018Revision Number1Supersedes date08-Apr-2025

9.1. Information on basic physical and chemical properties

Physical state Liquid Appearance Paste

Color No information available

Odor Characteristic

Odor threshold No information available

<u>Property</u> <u>Values</u> <u>Remarks • Method</u>

pH 8.0 - 9.0

pH (as aqueous solution)
No data available
None known
Melting point / freezing point
No data available
None known

Initial boiling point and boiling range100 °C / 212 °F

Flash point > 100 °C / 212 °F

Evaporation rateNo data availableNone knownFlammabilityNo data availableNone knownFlammability Limit in AirNone known

Upper flammability or explosive No data available

limits

Lower flammability or explosive No data available

limits

Vapor pressureNo data availableNone knownRelative vapor densityNo data availableNone knownRelative densityNo data availableNone known

Water solubility Insoluble in water

Solubility(ies) No data available None known **Partition coefficient** No data available None known **Autoignition temperature** No data available None known **Decomposition temperature** No data available None known Kinematic viscosity No data available None known Dynamic viscosity No data available None known

9.2. Other information

Explosive properties
Oxidizing properties
No information available

VOC content No information available

Density 1.23 g/cm³

Bulk density No information available

10. Stability and Reactivity

10.1. Reactivity

Reactivity No information available.

10.2. Chemical stability

Chemical stability Stable under normal conditions.

10.3. Possibility of hazardous reactions

Possibility of hazardous reactions None under normal processing.

10.4. Conditions to avoid

US - EN Page 7 / 14

BOSTIK WOOD TACKRevision date15-Oct-2018Revision Number1Supersedes date08-Apr-2025

Conditions to avoid Do not freeze.

10.5. Incompatible materials

Incompatible materialsNone known based on information supplied.

10.6. Hazardous decomposition products

Hazardous decomposition products Carbon monoxide Carbon dioxide (CO2) Hydrocarbons

11. Toxicological information

11.1. Information on toxicological effects

Product Information

Inhalation Specific test data for the substance or mixture is not available. May cause irritation of

respiratory tract.

Eye contact Causes serious eye irritation. May cause redness, itching, and pain.

Skin contact May cause sensitization by skin contact. Repeated or prolonged skin contact may cause

allergic reactions with susceptible persons. May cause irritation. Prolonged contact may

cause redness and irritation. Causes mild skin irritation.

Ingestion Ingestion may cause gastrointestinal irritation, nausea, vomiting and diarrhea.

Symptoms related to the physical, chemical and toxicological characteristics

Symptoms Itching. Rashes. Hives. May cause redness and tearing of the eyes. Prolonged contact may

cause redness and irritation.

Acute toxicity

Numerical measures of toxicity

The following values are calculated based on chapter 3.1 of the GHS document

 ATEmix (oral)
 134,423.50 mg/kg

 ATEmix (dermal)
 154,155.40 mg/kg

 ATEmix (inhalation-gas)
 >20000 ppm

 ATEmix (inhalation-dust/mist)
 >5 mg/l

 ATEmix (inhalation-vapor)
 >20 mg/l

Component Information

Chemical name	Oral LD50	Dermal LD50	Inhalation LC50
Limestone 1317-65-3	>5000 mg/kg (Rattus)	-	-
Carbonic acid, magnesium salt (1:1) 546-93-0	>2000 mg/Kg Rat	-	-
Rosin 8050-09-7	>2000 mg/Kg (Rattus)	> 2500 mg/kg (Oryctolagus cuniculus)	=1.5 mg/L (Rattus) 4 h
Ethanolamine 141-43-5	=1720 mg/kg (Rattus)	= 1 mL/kg (Oryctolagus cuniculus) = 1000 mg/kg	> 1.3013 mg/L (Rat)6 h

US - EN Page 8 / 14

BOSTIK WOOD TACKRevision date15-Oct-2018Revision Number1Supersedes date08-Apr-2025

		(Oryctolagus cuniculus)	
Quartz 14808-60-7	>2000 mg/kg (Rattus)	-	-
Poly(oxy-1,2-ethanediyl), .alpha(4-nonylphenyl)omega. -hydroxy-, branched 127087-87-0	=1310 mg/kg (Rattus)	LD50, Rabbit, 1,883 - 4,164 mg/kg	-
Vinyl acetate 108-05-4	=2900 mg/kg (Rattus)	= 2335 mg/kg (Oryctolagus cuniculus)	=11.4 mg/L (Rattus) 4 h = 3680 ppm (Rattus) 4 h
Zinc pyrithione 13463-41-7	=177 mg/kg (Rattus)	>2000 mg/kg (Oryctolagus cuniculus) (EPA OPP 81-2)	4h = 1.03 mg/L (Rattus) 4 h
reaction mass of 5-chloro-2-methyl-2H-isothiazol- 3-one and 2-methyl-2H-isothiazol-3-one (3:1) [C(M)IT/MIT] 55965-84-9	66 mg/kg (Rat)	LD50 = 8141 mg/kg (Rat) OECD 402	= 0.33 mg/L (Rat) 4h

Delayed and immediate effects as well as chronic effects from short and long-term exposure

Skin corrosion/irritation

Classification based on data available for ingredients. Causes mild skin irritation.

Vinyl acetate (108-05-4)

Method	Species	Exposure route	Effective dose	Exposure time	Results
OECD Test No. 404: Acute	Rabbit	Dermal			Non-irritant
Dermal Irritation/Corrosion					

Serious eye damage/eye irritation Classification based on data available for ingredients. Causes serious eye irritation.

Vinyl acetate (108-05-4)

Method	Species	Exposure route	Effective dose	Exposure time	Results
OECD Test No. 405: Acute	Rabbit	eye			Non-irritant
Eye Irritation/Corrosion					

Respiratory or skin sensitization May cause an allergic skin reaction.

Germ cell mutagenicity Based on available data, the classification criteria are not met.

Vinyl acetate (108-05-4)

Method	Species	Results
OECD Test No. 473: In vitro Mammalian	Human lymphocytes, in vitro	Mutagenic
Chromosome Aberration Test		-
OECD Test No. 471: Bacterial Reverse Mutation		Not mutagenic in AMES Test
Test		-

Carcinogenicity

This product contains substances which in their raw state are powder form, however in this product they are in a non-respirable form. Inhalation of powder/dust particles is unlikely to occur from exposure to this product. Contains a known or suspected carcinogen. Classification based on data available for ingredients. Suspected of causing cancer.

The table below indicates whether each agency has listed any ingredient as a carcinogen.

US - EN Page 9 / 14

BOSTIK WOOD TACK Revision date 15-Oct-2018 **Revision Number** 1 Supersedes date 08-Apr-2025

Chemical name	ACGIH	IARC	NTP	OSHA
Quartz	A2	Group 1	Known	X
14808-60-7				
Vinyl acetate	A3	Group 2B	-	X
108-05-4		-		

Legend
ACGIH (American Conference of Governmental Industrial Hygienists)

A3 - Animal Carcinogen

IARC (International Agency for Research on Cancer)

Group 2B - Possibly Carcinogenic to Humans

Occupational Safety and Health Administration of the US Department of Labor

X - Present

Vinyl acetate (108-05-4)

Method	Species	Results
OECD Test No. 453: Combined Chronic	Rat	Carcinogenic
Toxicity/Carcinogenicity Studies		_

Reproductive toxicity

Based on available data, the classification criteria are not met.

Vinyl acetate (108-05-4)

Method	Species	Results
OECD Test No. 416: Two-Generation	Rat	NOAEL 100 mg/kg bw/day
Reproduction Toxicity		

STOT - single exposure

Based on available data, the classification criteria are not met.

STOT - repeated exposure

Based on available data, the classification criteria are not met.

Vinyl acetate (108-05-4)

Method	Species	Exposure route	Effective dose	Exposure time	Results
OECD Test No. 408: Repeated Dose 90-Day Oral Toxicity Study in Rodents	Mouse, female	Oral		91 days	NOAEL: 281 mg/kg
OECD Test No. 408: Repeated Dose 90-Day Oral Toxicity Study in Rodents	Mouse, male	Oral		91 days	NOAEL 285 mg/kg
OECD Test No. 408: Repeated Dose 90-Day Oral Toxicity Study in Rodents	Rat, male	Oral		91 days	NOAEL 684 mg/kg
OECD Test No. 408: Repeated Dose 90-Day Oral Toxicity Study in Rodents	Rat, female	Oral		91 days	NOAEL 810 mg/kg

Aspiration hazard Based on available data, the classification criteria are not met.

Other adverse effects No information available. Interactive effects No information available.

US - EN Page 10 / 14

BOSTIK WOOD TACKRevision date15-Oct-2018Revision Number1Supersedes date08-Apr-2025

12. Ecological information

12.1. Toxicity

Ecotoxicity

Chemical name	Algae/aquatic plants	Fish	Toxicity to microorganisms	Crustacea
Limestone 1317-65-3	CE50 (72h) >200mg/L Algae (Desmondesmus subspicatus)	CL50 (96h)>10000mg/L (Oncorhynchus mykiss)	-	CE50 (48h) >1000 mg/L Daphnia Magna
Rosin 8050-09-7	EC50: =400mg/L (72h, Desmodesmus subspicatus)	LC50 (96h) >10mg/L (Danio rerio)	EC50 = 31.5 mg/L 30 min	EC50 48 h >100 mg/L (Daphnia magna)
Ethanolamine 141-43-5	EC50: =15mg/L (72h, Desmodesmus subspicatus)	LC50: 300 - 1000mg/L (96h, Lepomis macrochirus) LC50: 114 - 196mg/L (96h, Oncorhynchus mykiss) LC50: =227mg/L (96h, Pimephales promelas) LC50: =3684mg/L (96h, Brachydanio rerio) LC50: >200mg/L (96h, Oncorhynchus mykiss)	EC50 = 110 mg/L 17 h EC50 = 12200 mg/L 2 h EC50 = 13.7 mg/L 30 min	EC50: =65mg/L (48h, Daphnia magna)
Vinyl acetate 108-05-4	-	LC50 96 h = 14 mg/L (Pimephales promelas static)	EC50 = 2080 mg/L 5 min	EC50 48 h = 12.6 mg/L (Daphnia magna)
Zinc pyrithione 13463-41-7	EC50 (72hr) 0.0013 mg/l (Skeletonema costatum) (ISO 10253) 0.051 mg/l (Pseudokirchneriella subcapitata) (OECD 201)	EC50(96hr) 0.0104 mg/l (Brachydanio rerio) (OECD 203)	-	EC50 (48h) =0.038 mg/L Crustaceans (Ilyocypris dentifera)
reaction mass of 5-chloro-2-methyl-2H-isot hiazol-3-one and 2-methyl-2H-isothiazol-3- one (3:1) [C(M)IT/MIT] 55965-84-9	EC50 (72h) =0.048 mg/L (Pseudokirchneriella subcapitata) (OECD 201)	EC50 (96h) = 0.22 mg/L (Oncorhynchus mykiss) (OECD 211)	-	EC50 (48h) =0.1 mg/L (Daphnia magna) (OECD 202)

12.2. Persistence and degradability

Persistence and degradability No information available.

12.3. Bioaccumulative potential

Bioaccumulation There is no data for this product.

Component Information

Chemical name	Partition coefficient
Limestone 1317-65-3	0.9
Rosin	7.7

US - EN Page 11 / 14

BOSTIK WOOD TACKRevision date15-Oct-2018Revision NumberSupersedes date08-Apr-2025

8050-09-7	
Ethanolamine 141-43-5	-2.3
Poly(oxy-1,2-ethanediyl), .alpha(4-nonylphenyl)omegahydroxy-, branched 127087-87-0	5.669
Vinyl acetate 108-05-4	0.73
Zinc pyrithione 13463-41-7	1.21
reaction mass of 5-chloro-2-methyl-2H-isothiazol-3-one and 2-methyl-2H-isothiazol-3-one (3:1) [C(M)IT/MIT] 55965-84-9	0.7

12.4. Mobility in soil

Mobility No information available.

Other adverse effects

Other adverse effects No information available.

13. Disposal considerations

13.1. Waste treatment methods

Waste from residues/unused products

It is the responsibility of the waste generator to determine the toxicity and physical properties of the material generated to determine the proper waste identification and

disposal methods in compliance with applicable regulations.

Contaminated packaging Dispose of in accordance with federal, state and local regulations.

14. Transport information

Note: Keep from freezing.

DOT Not regulated

<u>IATA</u> Not regulated

IMDG Not regulated

15. Regulatory Information

International Inventories

TSCA	Complies
IOCA	Complica
DSL	Complies

Legend:

TSCA - United States Toxic Substances Control Act Section 8(b) Inventory

DSL - Canadian Domestic Substances List

Complies - The components of this product are either listed or exempt from listing on inventory. Active

Not Listed - One or more components of this product are not listed on inventory.

US - EN Page 12 / 14

BOSTIK WOOD TACKRevision date15-Oct-2018Revision Number1Supersedes date08-Apr-2025

US Federal Regulations

SARA 313

Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 (SARA). This product contains a chemical or chemicals which are subject to the reporting requirements of the Act and Title 40 of the Code of Federal Regulations, Part 372.

Chemical name	CAS No.	SARA 313 - Threshold Values %
Vinyl acetate	108-05-4	0.1

SARA 311/312 Hazard Categories

Should this product meet EPCRA 311/312 Tier reporting criteria at 40 CFR 370, refer to Section 2 of this SDS for appropriate classifications.

16. Other Information

Key or legend to abbreviations and acronyms used in the safety data sheet

Legend

SVHC: Substances of Very High Concern for Authorization:
PBT: Persistent, Bioaccumulative, and Toxic (PBT) Substances
vPvB: Very Persistent and very Bioaccumulative (vPvB) Substances

STOT: Specific Target Organ Toxicity ATE: Acute Toxicity Estimate

LC50: 50% Lethal Concentration

LD50: 50% Lethal Dose

Legend Section 8: EXPOSURE CONTROLS/PERSONAL PROTECTION

TWA TWA (time-weighted average) STEL STEL (Short Term Exposure Limit)

Ceiling Maximum limit value Sk* Skin designation

Prepared By Product Stewardship and Regulatory Affairs.

Revision date 15-Oct-2018

Revision Note SDS sections updated. 2. 3. 7. 8. 11.

Disclaimer

All information contained herein is believed to be accurate as of the date of publication, is provided "as-is" and is subject to change without notice. This is not a warranty, an agreement, or substitute for expert or professional advice. Bostik Inc. ("Company") expressly disclaims and assumes no liability for the use of the products or reliance on this information. It is the sole responsibility of the user to determine the suitability of any products for user's application(s). NO WARRANTY OF FITNESS FOR ANY PARTICULAR PURPOSE OR ANY OTHER WARRANTY, EXPRESS OR IMPLIED (INCLUDING SUITABILITY FOR USE IN ANY MEDICAL DEVICE OR MEDICAL APPLICATION), IS MADE CONCERNING THE PRODUCTS OR THE INFORMATION PROVIDED HEREIN. The information provided relates only to the specific products designated herein and may not be valid where such products are used in combination with other materials or in any process. The performance of the product, its shelf life, and application characteristics depends on many variables, and changes in these variables can impact product performance. You are responsible to test the suitability of any product in advance for any intended use or application and before commercialization. Nothing herein shall be construed as a license for the use of any product in a manner that might infringe any patent and it should not be construed as an inducement to infringe any patent. Please carefully review the Safety Data Sheet for the product.

The Company adheres to a strict policy that applies to the use of any of its products in medical device applications. This policy can be found at

https://www.arkema.com/global/en/social-responsibility/innovation-and-sustainable-solutions/responsible-product-mana gement/medical-device-policy/ which is incorporated herein by reference and made a part hereof. Except as expressly

US - EN Page 13 / 14

Revision date 15-Oct-2018

Supersedes date 08-Apr-2025

BOSTIK WOOD TACK
Revision Number 1

authorized, the Company (i) has designated specific medical grade compositions for products used in medical device applications and Company products not so designated are not authorized for use in medical device applications and (ii) strictly prohibits the use of any of its products in medical device applications that are implanted in the body or in contact with bodily fluids or tissues for greater than 30 days. The Company does not design, manufacture and/or directly sell any medical devices. The Company does not co-design, or offer assistance to any purchaser of its products, in their design, manufacture and/or sale of products for medical devices. It is the sole responsibility of the manufacturer of medical devices to determine the suitability of all raw material, products and components, including any medical grade products, in order to ensure that the medical device is safe for end-use and complies with all applicable legal and regulatory requirements and to conduct all necessary tests and inspections.

End of Safety Data Sheet

US - EN Page 14 / 14